

# Stormwater Service Assessment Program Report

Tampa City Council Update No. 11 - July 2019

Maintenance activities are reported based on service level frequency. Below is a list of the primary maintenance categories that are being tracked. Along with service level cycle times, we have also provided maintenance statistics for the quarter.

Operations and Maintenance Activities	Pre Fee Service Levels	Fee Target Service Levels	3 <sup>rd</sup> Quarter FY19 & Year-to-Date Service Levels
Ditches	10-Year Cycle	7-Year Cycle	5.9-Year Cycle (3 <sup>rd</sup> Qtr.) 5.0-Year Cycle (Y.T.D)
Ponds	Minimal	3-Year Cycle	3-Year Cycle (3 <sup>rd</sup> Qtr.) 3-Year Cycle (Y.T.D)
Pipes	10-Year Cycle	7-Year Cycle	6.6-Year Cycle (3 <sup>rd</sup> Qtr.) 5.1-Year Cycle (Y.T.D)
Outfalls	15-Year Cycle	5-Year Cycle	45-Year Cycle (3 <sup>rd</sup> Qtr.) 3.3-Year Cycle (Y.T.D)
Pumps	Low Preventative Maintenance	Annual Preventative Maintenance	1-Year Cycle
Street Sweeping	90-Day Cycle	60-Day Cycle	58-Day Cycle (3 <sup>rd</sup> Qtr.) 56-Day Cycle (Y.T.D)
Operations and Maintenance Activities	3 <sup>rd</sup> Quarter Maintenance Statistics		
Ditches	42,316 linear feet of ditches maintained with 7,176 tons removed, 8 fallen trees removed, 441,765 linear feet of ditch mowed monthly. Installed 6,401 linear feet of ditch bank was stabilized.		
Ponds	4.5 tons of trash and illegal dumping have been disposed of, there have been 112 herbicide treatments to various ponds, 1 pond harvesting activity was conducted removing 105 tons of vegetation, 125 stormwater ponds mowed monthly. 16 LF of fencing was repaired while replacing two gates for access.		
Pipes	105,498 linear feet of storm drain pipe inspected and maintained, 1,504 storm drain inlets and manholes inspected and maintained with 356 tons of debris removed. 37 sediment traps cleaned removing 76 tons of debris. 38 cave-ins and 44 inlet tops repaired.		
Outfalls	Three outfalls maintained. During the summer months, outfall maintenance drops significantly due to the higher-than-normal tides. Maintenance will increase in the fall.		
Pumps	Preventative Maintenance provided to all thirteen (13) stormwater pump stations. Continuous monitoring is ongoing with proactive maintenance and inspections.		
Street Sweeping	5,444 curb miles were swept, approximately 1,062 tons of debris removed.		

### 1101 E. River Cove St

### **Before**



After



## **Fielding Right-of-Way Ditch**

Before



After



## **Lemon St Ditch Lois Ave to West Shore Blvd**



### Before





#### After

