



# CITY OF TAMPA

Bob Buckhorn, Mayor

CONTRACT ADMINISTRATION DEPARTMENT

David L. Vaughn, AIA, Director

## ADDENDUM NO. 2

DATE: September 4, 2014

Contract 14-C-00030; Whatley Ditch Rehabilitation (North Boulevard to Hillsborough River)

Bidders on the above referenced project are hereby notified that the following addendum is made to the Contract Documents. BIDS TO BE SUBMITTED SHALL CONFORM TO THIS NOTICE.

Item 1: Replace Proposal Pages P-3 and P-4 with the attached pages P-3R and P-4R.

Item 2: Replace Contract Item 0550-1 with the following:

### CONTRACT ITEM 0550-1 – CHAIN LINK FENCING

The Contractor shall furnish all labor, materials, services, equipment and appurtenances to remove and reinstall the existing Chain Link Fence and to install the new Chain Link Fence in the proposed new locations all as shown in the Contract Plans.

The work includes all brush removal, excavation, bracing, filling, grading, concrete footing, bottom and top wire, cross bracing, locking assemblies, posts wire fabric, and all appurtenant work complete in place.

The quantity of fencing work to be measured for payment will be the length of fencing within payment limits as shown on the Plans, or as specified and directed by the Engineer.

The removal and reinstallation of existing Fencing shall conform to the requirements of the Workmanship and Materials Section 550 – Remove & Reinstall Ex. Chain Link Fence.

For the installation of new Chain Link Fence, the Contractor shall refer to the latest version of FDOT Workmanship and Materials Section 550 – Type B Chain Link Fencing.

Payment for both existing and newly proposed Chain Link Fencing work will be made at the Contract Item Unit Price per lineal feet of fence.

All other provisions of the Contract Documents and Specifications not in conflict with this Addendum shall remain in full force and effect. Questions are to be e-mailed to Contract Administration@tampagov.net.

*Jim Greiner*

Jim Greiner, P.E., Contract Management Supervisor

Item No.	Description	Unit	Approx. Quantity	Unit Price in Words	Unit Price	Total Computed Price
0100-1	Contingency	LS	1	One Hundred Twelve Thousand Five Hundred Dollars	\$ 112,500.00	\$ 112,500.00
0101-1	Mobilization	LS	1		\$	\$
0102-1	Maintenance of Traffic	LS	1		\$	\$
0104-1	Erosion Control, Tree Protection, & Turbidity Barrier	LS	1		\$	\$
0105-1	Root Pruning	LS	1		\$	\$
0105-2	Tree Removal	LS	1		\$	\$
0108-1	Dewatering and By-Pass Pumping	LS	1		\$	\$
0110-1	Clearing Ditch and Debris Removal	LS	1		\$	\$
0110-2	Remove Ex. Sheet Metal Fencing/Wall	LF	100		\$	\$
0110-3	Demo and Remove Ex. Riprap & Granite Curb Retaining Wall	LF	515		\$	\$
0112-1	Landscape	EA	61		\$	\$
0120-1	Grading Slope	SY	2,840		\$	\$
0120-4	Removal & Disposal of Unsuitable Subsoil - Allowance	LS	1		\$	\$
0142-1	Imported Soil Fill Material	CY	2,400		\$	\$
0350-1	Concrete Retaining Wall Penetrations	CY	3		\$	\$
0425-1	City of Tampa Brick Manhole	EA	1		\$	\$
0430-1	Concrete Pipe Culvert (15-Inch Diameter) -Class IV	LF	11		\$	\$

Item No.	Description	Unit	Approx. Quantity	Unit Price in Words	Unit Price	Total Computed Price
0430-2	6" PVC Stormpipe	LF	10		\$	\$
0524-1	Enviromat EL 400 Fabric Formed Concrete	SY	560		\$	\$
0530-1	Rubble Rip Rap	TN	2		\$	\$
0535-1	Box Culvert Headwall & Wingwall	EA	1		\$	\$
0548-1	Retaining Wall System (Interlocking Block Wall)	SF	16,000		\$	\$
0548-2	Retaining Wall System (Gabion Wall)	CY	95		\$	\$
0548-3	Reno Mats (Ditch Bottom)	CY	355		\$	\$
0550-1	Remove & Reinstall Ex. Chainlink Fence	LF	1,728		\$	\$
0570-1	Hydroseed (Bahia at Reno Mats, Gabions and Enviromats)	SY	1,785		\$	\$
0570-2	Hydroseed (Hydramax-Bahia Mix at bank slope)	SY	1,620		\$	\$
0590-1	Temporary Irrigation	LS	1		\$	\$
					TOTAL \$	