



City of Tampa
Jane Castor, Mayor

Contract Administration Department

306 East Jackson Street, 4N
Tampa, FL 33602

Office (813) 274-8116
Fax: (813) 274-7368

ADDENDUM 1

DATE: April 10, 2023

Contract: 22-C-00050; Downtown Interchange Wastewater Collection System Rehabilitation by CIPP
Lining

Bidders on the above referenced project are hereby notified that the following addendum is made to the Contract Documents. BIDS TO BE SUBMITTED SHALL CONFORM TO THIS NOTICE.

Item 1: Replace Proposal page P-2 with the attached Proposal page P-2R.

Note: The Units have been corrected for Item Nos. 0427.4720 and 0430.5310.

Item 2: Change the title of Contract Item 0430 Series to read:

CONTRACT ITEM 0427 through 0430 SERIES – CHEMICAL GROUTING LATERAL AFTER REINSTATEMENT

All other provisions of the Contract Documents and Specifications not in conflict with this Addendum shall remain in full force and effect. Questions are to be e-mailed to
ContractAdministration@tampagov.net.

Jim Greiner

Jim Greiner, P.E., Contract Management Supervisor

Downtown Interchange Wastewater Collection System Rehabilitation by CIPP Lining

Contract; 22-C-00050

Item No.	Item	Quantity	Unit	Unit Price in Words	Unit Price	Total
100	Contingency	1	LS	Fifty Thousand Dollars	\$50,000.00	\$50,000
102	Maintenance of Traffic	1	LS			
0408.2360	Cured in Place Pipe for 8" Dia. Gravity Sewer (.236 inch thick)	9,590	LF			
0410.2950	Cured in Place Pipe for 10" Dia. Gravity Sewer (.295 inch thick)	254	LF			
0601.08	Hydraulic Cleaning & Inspection of 8" Dia. Gravity Sewer	9,560	LF			
0601.10	Hydraulic Cleaning & Inspection of 10" Dia. Gravity Sewer	254	LF			
9000	Sewer Bypass with Tanker Truck	500	Hrs			
9050.08	Sewage Bypass Pumping for 8" Dia. Sewer	9,590	LF			
9050.10	Sewage Bypass Pumping for 10" Dia. Sewer	254	LF			
0602	Mechanical Cleaning and Inspection of 8" Dia Gravity Sewer	1,918	LF			
0621.08	Cleaning & Inspection of Tuberculated Cast Iron or Ductile Iron Sewer , 8" Dia.	30	LF			
2050	Reconnect Service Connections	242	EA			
0427.4720	Chemical Grout Unit - chemical grout lateral post liner install - 8-inch gravity pipe diameter	239	EA			
0430.5310	Chemical Grout Unit - chemical grout lateral post liner install - 10-inch gravity pipe diameter	3	EA			
4800	Manhole Rehabilitation by Coating System min. 250 mils thickness	2,751	SF			
4600	Cast Iron Frame and Cover	14	EA			
0700	Disposal of Debris	9	CY			
TOTAL						