FY 20
Stormwater Service Assessment Program Report

Tampa City Council Update No. 17 - March 2021

Maintenance activities are reported based on service level frequency. Below is a list of the primary maintenance categories that are being tracked. Along with service level cycle times, we have also provided maintenance statistics for the quarter.

Operations and Maintenance Activities	Pre Fee Service Levels	Fee Target Service Levels	1st Quarter FY21 & Year-to-Date Service Levels
Ditches	10-Year Cycle	7-Year Cycle	8.7-Year Cycle (1st Qtr.) 7.7-Year Cycle (Y.T.D)
Ponds	Minimal	3-Year Cycle	3-Year Cycle (1st Qtr.) 3-Year Cycle (Y.T.D)
Pipes	10-Year Cycle	7-Year Cycle	6.1-Year Cycle (1st Qtr.) 6.3-Year Cycle (Y.T.D)
Outfalls	15-Year Cycle	5-Year Cycle	N/A-Year Cycle (1st Qtr.) 4.7-Year Cycle (Y.T.D)
Pumps	Low Preventative Maintenance	Annual Preventative Maintenance	1-Year Cycle
Street Sweeping	90-Day Cycle	60-Day Cycle	48-Day Cycle (1st Qtr.) 54-Day Cycle (Y.T.D)

Operations and Maintenance Activities	1st Quarter Maintenance Statistics
Ditches	28,417 linear feet of ditches maintained with 2,579 tons removed, 72 fallen trees removed, 441,765 linear feet of ditch mowed monthly with 13.8 tons of trash removed.
Ponds	4.7 tons of trash and illegal dumping have been disposed of, there have been 116 herbicide treatments to various ponds, 126 stormwater ponds mowed monthly. 7,253 linear feet of pond fencing replaced.
Pipes	113,871 linear feet of storm drainage pipe inspected and maintained, 2,319 storm drain inlets and manholes inspected and maintained with 417 tons of debris removed. 38 cave-ins and 34 inlet tops repaired.
Outfalls	Outfall inspections and maintenance were suspended due to high tides. Our year to date cycle of inspections and maintenance are still at an acceptable level.
Pumps	Preventative Maintenance provided to all thirteen (13) stormwater pump stations. Proactive maintenance and inspections totaled 328 Manhours.
Street Sweeping	6,550 curb miles were swept, approximately 1,467 tons of debris removed.

Port Tampa Park

Before

After

Before

After

Fitzgerald Right-Of-Way Ditch

Before

After

Before

After

Bayshore Outfall Cleaning

Before

After



Before

After