



## Section C

# Stormwater Service Assessment Program Report

### Tampa City Council Update No. 29 - February 2024

Maintenance activities are reported based on service level frequency. Below is a list of the primary maintenance categories that are being tracked. Along with service level cycle times, we have also provided maintenance statistics for the quarter.


Operations and Maintenance Activities	Pre Fee Service Levels	Fee Target Service Levels	1 <sup>st</sup> Quarter FY24 & Year to Date Service Levels
Ditches	10-Year Cycle	7-Year Cycle	13.2-Year Cycle (1 <sup>st</sup> Qtr.) 7.4-Year Cycle (Y.T.D)
Ponds	Minimal	3-Year Cycle	3-Year Cycle (1 <sup>st</sup> Qtr.) 3-Year Cycle (Y.T.D)
Pipes	10-Year Cycle	7-Year Cycle	2.1-Year Cycle (1 <sup>st</sup> Qtr.) 2.8-Year Cycle (Y.T.D)
Outfalls	15-Year Cycle	5-Year Cycle	0.5-Year Cycle (1 <sup>st</sup> Qtr.) 1.0-Year Cycle (Y.T.D)
Pumps	Low Preventative Maintenance	Annual Preventative Maintenance	1-Year Cycle
Street Sweeping	90-Day Cycle	60-Day Cycle	40-Day Cycle (1 <sup>st</sup> Qtr.) 50-Day Cycle (Y.T.D)
Operations and Maintenance Activities	4 <sup>th</sup> Quarter Maintenance Statistics		
Ditches			
Ponds			
Pipes			
Outfalls	479 outfalls were inspected and maintained.		
Pumps	Preventative Maintenance provided to all thirteen (13) stormwater pump stations. Proactive maintenance and inspections totaled 17 Manhours.		
Street Sweeping	7,096 curb miles were swept, approximately 1,299 tons of debris removed.		

Activity Type	1 <sup>st</sup> Quarter Department Activities Relating to Findings Pertaining to Ditches/Swales
Micro Projects	There is no new activity for project development to remedy historic activity.
Maintenance Activities	There are no locations that are currently being reviewed by Operations staff.

Rocky Point Outfall Cleaning



Before



After

**1513 W. Busch Blvd. Ditch Grading and Vegetation Removal**



**Before**



**After**

**S. Edison Ave. at W. Cypress St. Inlet Top Repair**



**Before**



**During**



**After**



### North Tampa Inlet Cleaning



Before



After

### 4806 W. Estrella St. Inlet Basket Cleaning



Before



After