



**Mobility Department**

**Operations Division**

**Stormwater Maintenance Report**

**February 2026**

## Stormwater Calls for Service

Calls For Service - Calendar Year 2025 vs. 2026	Totals 2025	Totals 2026
Cave-In or Sinking Area Repair	650	58
Curb or Street Gutter Repair Request	122	23
Ditch or Retention Pond Maintenance	436	29
Erosion Issues	41	8
Flooding Issues	284	6
Improper Drainage or Backup Issues	585	21
Manhole, Grate, Inlet Top or Headwall Issues	224	36
Stormwater Service Request	506	71
Street Sweeping Request	9	1
Pond Maintenance	7	0
<b>Total Calls for Service</b>	<b>2,864</b>	<b>253</b>
*includes phone calls, emails, and Tampa Connect messages		
Calls by Month	Totals 2025	Totals 2026
January	214	111
February	197	142
March	241	
April	191	
May	199	
June	565	
July	360	
August	311	
September	220	
October	153	
November	91	
December	122	
<b>Total Calls for Service</b>	<b>2,864</b>	<b>253</b>
<b>Average Calls Per Month</b>	<b>239</b>	<b>126</b>

Calls For Service - February 2026	Totals
Cave-In or Sinking Area Repair	29
Curb or Street Gutter Repair Request	18
Ditch or Retention Pond Maintenance	13
Erosion Issues	3
Flooding Issues	3
Improper Drainage or Backup Issues	14
Manhole, Grate, Inlet Top or Headwall Issues	18
Stormwater Service Request	43
Street Sweeping Request	1
Pond Maintenance	0
<b>Total Calls for Service</b>	<b>142</b>
*includes phone calls, emails, and Tampa Connect messages	

# February 2026

## Stormwater Maintenance Report

### Tampa City Council Update

Below is a list of the primary maintenance categories that are being tracked. We have provided maintenance statistics for the month along with the maintenance locations. Also attached is a Detail Productivity Report that shows all locations where work was performed.

February Work Locations and Descriptions			
Temple Crest	Historic Hyder Park Neighborhood Association Inc.	Sunset Park Area Homeowners Association Inc.	South Seminole Heights Civic Association, Inc.
Forest Hills	Terrace Park	Drew Park Advisory Committee	Riverside Heights Civic Association
Wellswood Civic Association, Inc.			

February Work Accomplishments			
Maintenance Activities	Accomplishment	Unit of Measure	Description
Ditches	3,529	Linear Feet Dug Out (In-house)	Ditches are mowed monthly, large trash is picked up, fallen trees and branches are removed, capacity is restored.
	3,710	Linear Feet Dug Out (Contractor)	
	1,005.4	Tons of Debris Removed	
	83	Miles Mowed	
Ponds	8.17	Tons of Trash Picked Up	Ponds are mowed monthly, large trash is picked up, fallen trees and branches are removed, capacity is restored, aquatic vegetation is treated.
	127	Ponds Mowed	
	2.63	Tons of Trash Removed	
	116	Ponds Sprayed	
Pipes	54	Feet of Fencing Repaired	Pipes and structures are inspected and maintained with heavy equipment, in-house personnel, and contractors. Pipe is also reconstructed or installed new.
	63,993	Linear Feet (In-house)	
	77.11	Tons of Debris Removed	
Cave-ins	406	Feet of Pipe Constructed	
	11	Each (In-house)	
Structures	991	Each Maintained (In-house)	
	5	Each Repaired (In-house)	
	7	Each Headwalls Repaired (In-house)	

Outfalls			Outfalls are inspected and maintained with heavy equipment, in-house personnel, and contractors.
Pumps Stations	Monthly inspections complete. Conversion from radio to cellular scheduled for early March. Worked with engineering on stormwater resiliency plan. Alline and Curiosity Creek generator PMs complete and load bank tested. Portable generator load bank tested.		
Street Sweeping			Street Sweeping is conducted with leased sweepers and in-house personnel.
			Sulfur Springs
Gandy Civic Association	Drew Park	Riverside Heights Civic Association	Palmetto Beach Community
Monthly pump station inspections and maintenance. Conversion from radio to cellular connectivity at several stations.			

**CALLS FOR SERVICE SHOULD BE DIRECTED TO**

**813-274-3101**

**24/7**

**Pond Maintenance – 11315 N. 30<sup>th</sup> St.**



**Before**



**During**

**Pond Maintenance – 11315 N. 30<sup>th</sup> St. (cont.)**




**After**

**Cave In Repair – 5210 Bon Vivant Dr.**



**Before**



**During**



**During**



**During**



**After**

**Headwall Repair – 1905 W. Fern St.**



**Before**



**During**

**Headwall Repair – 1905 W. Fern St. (cont.)**



**During**



**After**

**Inlet Top Repair – 1517 W. Barr Drive**



**Before**



**During**



**After**


**Outfall Cleaning – 499 Bosphorous Ave.**



**Before**

**After**

**Outfall Cleaning – 539 Suwanee Cir.**



**Before**

**After**