



Mobility Department

Operations Division

Stormwater Maintenance Report

January 2026



Stormwater Calls for Service

Calls For Service - Calendar Year 2025 vs. 2026	Totals 2025	Totals 2026
Cave-In or Sinking Area Repair	650	29
Curb or Street Gutter Repair Request	122	5
Ditch or Retention Pond Maintenance	436	16
Erosion Issues	41	5
Flooding Issues	284	3
Improper Drainage or Backup Issues	585	7
Manhole, Grate, Inlet Top or Headwall Issues	224	18
Stormwater Service Request	506	28
Street Sweeping Request	9	0
Pond Maintenance	7	0
Total Calls for Service	2,864	111
*includes phone calls, emails, and Tampa Connect messages		
Calls by Month	Totals 2025	Totals 2026
January	214	111
February	197	
March	241	
April	191	
May	199	
June	565	
July	360	
August	311	
September	220	
October	153	
November	91	
December	122	
Total Calls for Service	2,864	111
Average Calls Per Month	239	111

Calls For Service - January 2026	Totals
Cave-In or Sinking Area Repair	29
Curb or Street Gutter Repair Request	5
Ditch or Retention Pond Maintenance	16
Erosion Issues	5
Flooding Issues	3
Improper Drainage or Backup Issues	7
Manhole, Grate, Inlet Top or Headwall Issues	18
Stormwater Service Request	28
Street Sweeping Request	0
Pond Maintenance	0
Total Calls for Service	111
*includes phone calls, emails, and Tampa Connect messages	



January 2026

Stormwater Maintenance Report

Tampa City Council Update

Below is a list of the primary maintenance categories that are being tracked. We have provided maintenance statistics for the month along with the maintenance locations. Also attached is a Detail Productivity Report that shows all locations where work was performed.

January Work Locations and Descriptions			
Interbay South of Gandy Civic Association	Port Tampa City, Inc.	Lowry Park Central	South Seminole Heights Civic Association, Inc.
Interbay South of Gandy Civic Association	Bayshore Beautiful	Terrace Park	Armory Gardens Civic Association
	Drew Park Advisory Committee	Armenia Gardens Estates	

January Work Accomplishments			
Maintenance Activities	Accomplishment	Unit of Measure	Description
Ditches	5,444	Linear Feet Dug Out (In-house)	Ditches are mowed monthly, large trash is picked up, fallen trees and branches are removed, capacity is restored.
	3,710	Linear Feet Dug Out (Contractor)	
	624.5	Tons of Debris Removed	
	83	Miles Mowed	
	6.93	Tons of Trash Picked Up	
Ponds	127	Ponds Mowed	Ponds are mowed monthly, large trash is picked up, fallen trees and branches are removed, capacity is restored, aquatic vegetation is treated.
	2.28	Tons of Trash Removed	
	116	Ponds Sprayed	
	29	Feet of Fencing Repaired	
Pipes	69,570	Linear Feet (In-house)	Pipes and structures are inspected and maintained with heavy equipment, in-house personnel, and contractors. Pipe is also reconstructed or installed new.
	4,244	Linear Feet (Contractor)	
	60.14	Tons of Debris Removed	
	239	Feet of Pipe Constructed	
Cave-ins	25	Each (In-house)	
	7	Each (Contractor)	
Structures	719	Each Maintained (In-house)	
	10	Each Repaired (In-house)	
	15	Each Maintained (Contractor)	
	3	Each Headwalls Repaired (In-house)	

January Work Accomplishments (cont.)

Maintenance Activities	Accomplishment	Unit of Measure	Description
Outfalls	22 147 42	Inspections (In-House) Inspections (Contractor) Maintained (Contractor)	Outfalls are inspected and maintained with heavy equipment, in-house personnel, and contractors.
Pumps Stations	Monthly inspections and PMs of all stations complete. EPC fuel tank inspections were completed. Established new POs for PMs/load bank testing. Closed Basing surge protector replaced. Robles Park rain gauge replaced. Worked with engineering on AMI pond inspections and dewatering.		
Street Sweeping	1,963 343.7	Curb Miles Tons of Debris Removed	Street Sweeping is conducted with leased sweepers and in-house personnel.

February Work Locations And Descriptions

Old Seminole Heights	Seminole Heights	Bayside West Neighborhood Association, Inc.	Palma Ceia Neighborhood Association
Wellswood Civic Association, Inc.	Drew Park	Riverside Heights Civic Association	

Monthly pump station inspections and maintenance. Work on eradicating pond vegetation from 29th and Poinsettia.

CALLS FOR SERVICE SHOULD BE DIRECTED TO

813-274-3101

24/7

Inlet Top Repair – 2900 El Prado Dr.



Before



During



After

Roadside Ditch Digging – 5702 N. Church Ave.



Before



After

Headwall Repair – 4103 W. Comanche Ave.



Outfall Cleaning – Interbay Blvd. at S. Nichol St.



Before



After

Outfall Cleaning – Bayshore at W. Asbury Pl.



Before



After