



Mobility Department

Operations Division

Stormwater Maintenance Report

July 2026



Stormwater Calls for Service

Calls For Service - Calendar Year 2025 vs. 2026	Totals 2025	Totals 2026
Cave-In or Sinking Area Repair	650	217
Curb or Street Gutter Repair Request	122	79
Ditch or Retention Pond Maintenance	436	170
Erosion Issues	41	29
Flooding Issues	284	74
Improper Drainage or Backup Issues	585	214
Manhole, Grate, Inlet Top or Headwall Issues	224	130
Stormwater Service Request	506	255
Street Sweeping Request	9	11
Pond Maintenance	7	1
Total Calls for Service	2,864	1,180
*includes phone calls, emails, and Tampa Connect messages		
Calls by Month	Totals 2025	Totals 2026
January	214	111
February	197	142
March	241	158
April	191	172
May	199	210
June	565	177
July	360	210
August	311	
September	220	
October	153	
November	91	
December	122	
Total Calls for Service	2,864	1,180
Average Calls Per Month	239	168

Calls For Service - July 2026	Totals
Cave-In or Sinking Area Repair	34
Curb or Street Gutter Repair Request	11
Ditch or Retention Pond Maintenance	31
Erosion Issues	6
Flooding Issues	18
Improper Drainage or Backup Issues	53
Manhole, Grate, Inlet Top or Headwall Issues	25
Stormwater Service Request	32
Street Sweeping Request	0
Pond Maintenance	0
Total Calls for Service	210
*includes phone calls, emails, and Tampa Connect messages	



July 2026

Stormwater Maintenance Report

Tampa City Council Update

Below is a list of the primary maintenance categories that are being tracked. We have provided maintenance statistics for the month along with the maintenance locations. Also attached is a Detail Productivity Report that shows all locations where work was performed.

July Work Locations and Descriptions			
Oak Grove	East Side Commercial	Gandy Civic Association	Culbreath Bayou Homeowners Association, Inc.
Sulfur Springs	Historic East Ybor and Gary Neighborhood Association	Sunset Park Area Homeowners Association, Inc.	East Tampa
Old Seminole Heights			

July Work Accomplishments			
Maintenance Activities	Accomplishment	Unit of Measure	Description
Ditches	6,742 747 83 8.64	Linear Feet Dug Out (In-house) Tons of Debris Removed Miles Mowed Tons of Trash Picked Up	Ditches are mowed monthly, large trash is picked up, fallen trees and branches are removed, capacity is restored.
Ponds	127 2.37 116 30 3,441	Ponds Mowed Tons of Trash Removed Ponds Sprayed Feet of Fencing Repaired Tons of Material Removed	Ponds are mowed monthly, large trash is picked up, fallen trees and branches are removed, capacity is restored, aquatic vegetation is treated.
Pipes	93,564 62.84 74	Linear Feet (In-house) Tons of Debris Removed (In-house) Feet of Pipe Constructed	Pipes and structures are inspected and maintained with heavy equipment, in-house personnel, and contractors. Pipe is also reconstructed or installed new.
Cave-ins	17	Each (In-house)	
Structures	1,235 15 5	Each Maintained (In-house) Each Repaired (In-house) Each Headwalls Repaired (In-house)	

July Work Accomplishments (cont.)			
Maintenance Activities	Accomplishment	Unit of Measure	Description
Outfalls	74	Inspections (In-House)	Outfalls are inspected and maintained with heavy equipment, in-house personnel, and contractors.
Pumps Stations	Monthly inspections complete. Worked with engineering on stormwater resiliency plan. July PMs complete. Major repair is ongoing to the radiator of the backup generator at Donut Pond. Constantly monitoring water levels and pumping locations down before rain events.		
Street Sweeping	1,857 314	Curb Miles Tons of Debris Removed	Street Sweeping is conducted with leased sweepers and in-house personnel.
August Work Locations And Descriptions			
Riverbend	Terrace Park	Drew Park Advisory Committee	Bayshore Beautiful Neighborhood Association, Inc.
Woodland Terrace	Wellswood Civic Association, Inc.	Sunset Park Area Homeowners Association, Inc.	Palma Ceia Neighborhood Association, Inc.

CALLS FOR SERVICE SHOULD BE DIRECTED TO

813-274-3101

24/7

Headwall Repair – 2113 W Burke St.



Before



After

Structure Repair – 8602 N. Arden Ave



Before



During



After

Ditch Digging – 2118 W Powhatan Ave



Before



After