



Mobility Department

Operations Division

Stormwater Maintenance Report

March 2026



Stormwater Calls for Service

Calls For Service - Calendar Year 2025 vs. 2026	Totals 2025	Totals 2026
Cave-In or Sinking Area Repair	650	87
Curb or Street Gutter Repair Request	122	34
Ditch or Retention Pond Maintenance	436	47
Erosion Issues	41	14
Flooding Issues	284	14
Improper Drainage or Backup Issues	585	51
Manhole, Grate, Inlet Top or Headwall Issues	224	49
Stormwater Service Request	506	111
Street Sweeping Request	9	4
Pond Maintenance	7	0
Total Calls for Service	2,864	411
*includes phone calls, emails, and Tampa Connect messages		
Calls by Month	Totals 2025	Totals 2026
January	214	111
February	197	142
March	241	158
April	191	
May	199	
June	565	
July	360	
August	311	
September	220	
October	153	
November	91	
December	122	
Total Calls for Service	2,864	411
Average Calls Per Month	239	137

Calls For Service - February 2026	Totals
Cave-In or Sinking Area Repair	29
Curb or Street Gutter Repair Request	11
Ditch or Retention Pond Maintenance	18
Erosion Issues	6
Flooding Issues	8
Improper Drainage or Backup Issues	30
Manhole, Grate, Inlet Top or Headwall Issues	13
Stormwater Service Request	40
Street Sweeping Request	3
Pond Maintenance	0
Total Calls for Service	158



Calls For Service - February 2026	Totals
*includes phone calls, emails, and Tampa Connect messages	

March 2026 Stormwater Maintenance Report Tampa City Council Update

Below is a list of the primary maintenance categories that are being tracked. We have provided maintenance statistics for the month along with the maintenance locations. Also attached is a Detail Productivity Report that shows all locations where work was performed.

March Work Locations and Descriptions

Ballast Point Neighborhood Association	Bayshore Beautiful Neighborhood Association, Inc.	Oakford Park Neighborhood Association, Inc.	Riverbend
Culbreath Bayou Homeowner's Association Inc.	Tampa Downtown Partnership, Inc.	Sulfur Springs	
Swann Estates Neighborhood Association, Inc.	Tampa Heights Civic Association, Inc.	Terrace Park	

March Work Accomplishments

Maintenance Activities	Accomplishment	Unit of Measure	Description
Ditches	7,844	Linear Feet Dug Out (In-house)	Ditches are mowed monthly, large trash is picked up, fallen trees and branches are removed, capacity is restored.
	188	Linear Feet Dug Out (Contractor)	
	850.72	Tons of Debris Removed	
	83	Miles Mowed	
	7.98	Tons of Trash Picked Up	
Ponds	127	Ponds Mowed	Ponds are mowed monthly, large trash is picked up, fallen trees and branches are removed, capacity is restored, aquatic vegetation is treated.
	2.67	Tons of Trash Removed	
	116	Ponds Sprayed	
	21	Feet of Fencing Repaired	
Pipes	82,161	Linear Feet (In-house)	Pipes and structures are inspected and maintained with heavy equipment, in-house personnel, and contractors. Pipe is also reconstructed or installed new.
	127.22	Tons of Debris Removed	
	71	Feet of Pipe Constructed	
16	Each (In-house)		
Structures	1,014 14 6	Each Maintained (In-house) Each Repaired (In-house) Each Headwalls Repaired (In-house)	

March Work Accomplishments

--	--	--	--

March Work Accomplishments (cont.)

Maintenance Activities	Accomplishment	Unit of Measure	Description
Outfalls	48 68	Inspections (In-House) Inspections (Contractor)	Outfalls are inspected and maintained with heavy equipment, in-house personnel, and contractors.
Pumps Stations	Monthly inspections complete. Conversion from radio to cellular is complete. Worked with engineering on stormwater resiliency plan.		
Street Sweeping	1,874 522.2	Curb Miles Tons of Debris Removed	Street Sweeping is conducted with leased sweepers and in-house personnel.

April Work Locations And Descriptions

Bayside West Neighborhood Association, Inc.	Port Tampa City, Inc. Civic Association	Lowry Park Central	Wellswood Civic Association, Inc.
Palma Ceia Neighborhood Association, Inc.	Armenia Gardens Estates	North Forest Hills	Drew Park Advisory Committee

CALLS FOR SERVICE SHOULD BE DIRECTED TO

813-274-3101

24/7

Ditch Maintenance - 4810 N. Himes Ave.



Before



During

After

Pond Maintenance - Lazy River Dr. at E. Regnas Ave.



Before



After

Cave In Repair - 2602 W. Sunset Dr.



Before



After

Headwall Repair - 3124 W. Douglas St.



Before



After

Inlet Top Repair - 8406 N. 12th St.



Before



During



During

After