



Mobility Department

Operations Division

Stormwater Maintenance Report

May 2026

Stormwater Calls for Service

Calls For Service - Calendar Year 2025 vs. 2026	Totals 2025	Totals 2026
Cave-In or Sinking Area Repair	650	159
Curb or Street Gutter Repair Request	122	57
Ditch or Retention Pond Maintenance	436	103
Erosion Issues	41	18
Flooding Issues	284	44
Improper Drainage or Backup Issues	585	126
Manhole, Grate, Inlet Top or Headwall Issues	224	92
Stormwater Service Request	506	187
Street Sweeping Request	9	7
Pond Maintenance	7	0
Total Calls for Service	2,864	793
*includes phone calls, emails, and Tampa Connect messages		
Calls by Month	Totals 2025	Totals 2026
January	214	111
February	197	142
March	241	158
April	191	172
May	199	210
June	565	
July	360	
August	311	
September	220	
October	153	
November	91	
December	122	
Total Calls for Service	2,864	793
Average Calls Per Month	239	159

Calls For Service - April 2026	Totals
Cave-In or Sinking Area Repair	44
Curb or Street Gutter Repair Request	15
Ditch or Retention Pond Maintenance	35
Erosion Issues	2
Flooding Issues	20
Improper Drainage or Backup Issues	33
Manhole, Grate, Inlet Top or Headwall Issues	21
Stormwater Service Request	38
Street Sweeping Request	2
Pond Maintenance	0
Total Calls for Service	210
*includes phone calls, emails, and Tampa Connect messages	



May 2026

Stormwater Maintenance Report

Tampa City Council Update

Below is a list of the primary maintenance categories that are being tracked. We have provided maintenance statistics for the month along with the maintenance locations. Also attached is a Detail Productivity Report that shows all locations where work was performed.

May Work Locations and Descriptions			
Sunset Park Area Homeowners Association, Inc.	Historic Belmont Heights Neighborhood Association	North Bon Air Neighborhood Association, Inc.	Seminole Heights
Palma Ceia Neighborhood Association, Inc.	Wellswood Civic Association, Inc.	Woodland Terrace	
Interbay – South of Gandy Civic Association	Riverside Heights Civic Association	Live Oaks Square	

May Work Accomplishments			
Maintenance Activities	Accomplishment	Unit of Measure	Description
Ditches	6,444 415.3 83 6.9	Linear Feet Dug Out (In-house) Tons of Debris Removed Miles Mowed Tons of Trash Picked Up	Ditches are mowed monthly, large trash is picked up, fallen trees and branches are removed, capacity is restored.
Ponds	127 3.5 116 20	Ponds Mowed Tons of Trash Removed Ponds Sprayed Feet of Fencing Repaired	Ponds are mowed monthly, large trash is picked up, fallen trees and branches are removed, capacity is restored, aquatic vegetation is treated.
Pipes	77,615 74.79 80	Linear Feet (In-house) Tons of Debris Removed (In-house) Feet of Pipe Constructed	Pipes and structures are inspected and maintained with heavy equipment, in-house personnel, and contractors. Pipe is also reconstructed or installed new.
Cave-ins	11	Each (In-house)	
Structures	1,131 28 301	Each Maintained (In-house) Each Repaired (In-house) Each Headwalls Repaired (In-house)	

May Work Accomplishments (cont.)

Maintenance Activities	Accomplishment	Unit of Measure	Description
Outfalls	25	Inspections (In-House)	Outfalls are inspected and maintained with heavy equipment, in-house personnel, and contractors.
Pumps Stations	Monthly inspections complete. Worked with engineering on stormwater resiliency plan. Reestablish points of contact with the generator rental company. Ordered and changed all pad locks to further restrict access to the stations. Major repair is ongoing to the radiator of the backup generator at Donut Pond.		
Street Sweeping		Curb Miles Tons of Debris Removed	Street Sweeping is conducted with leased sweepers and in-house personnel.

June Work Locations And Descriptions

Gandy Civic Association	Bayside West Neighborhood Association, Inc.	Palmetto Beach Community Association, Inc.	Temple Crest
Port Tampa City, Inc. Civic Association	Highland Pines Community Task Force, Inc.	Historic Ybor Neighborhood Civic Association, Inc.	

CALLS FOR SERVICE SHOULD BE DIRECTED TO


813-274-3101

24/7

Cave-In – 1105 West Adalee Street



Before



During



During



After

Pond Maintenance – Alluvial Fan Removal - N. 46th St. and E. Bougainvillea Ave.



Before



During

After

Structure Repair – 3626 S. Gardenia Ave.



Before



During



During



After

Ditch Digging and Washout Repair – 1212 W. Hollywood St.



Before



During

After